




SPS 2007 Operation Schedule



- Beam service for users (Tue -Wed : ABCD, Friday : A)
- Beam service shift codes : A = 09:00 - 14:00, B = 15:00 - 20:00, C = 21:00 - 02:00, D = 03:00 - 08:00
- Machine studies
- Machine opened for maintenance and installation
- Shut down

	SUN	MON	TUE	WED	THU	FRI	SAT
JAN	31	1	2	3	4	5	6
	7	8	9	10	11	12	13
	14	15	16	17	18	19	20
	21	22	23	24	25	26	27
	28	29	30	31			
FEB	4	5	6	7	8	9	10
	11	12	13	14	15	16	17
	18	19	20	21	22	23	24
	25	26	27	28			
MAR	4	5	6	7	8	9	10
	11	12	13	14	15	16	17
	18	19	20	21	22	23	24
	25	26	27	28	29	30	31
APR	1	2	3	4	5	6	7
	8	9	10	11	12	13	14
	15	16	17	18	19	20	21
	22	23	24	25	26	27	28
MAY	6	7	8	9	10	11	12
	13	14	15	16	17	18	19
	20	21	22	23	24	25	26
	27	28	29	30	31		
JUN	3					1	2
	10					8	9
	17					15	16
	24					22	23
JUL	1					6	7
	8					13	14
	15					20	21
	22					27	28
AUG	5					3	4
	12					10	11
	19	13	14	15	16	17	18
	26	20	21	22	23	24	25
SEP	2	3	4	5	6	7	8
	9	10	11	12	13	14	15
	16	17	18	19	20	21	22
	23	24	25	26	27	28	29
	30						
OCT	7	1	2	3	4	5	6
	14	8	9	10	11	12	13
	21	15	16	17	18	19	20
	28	22	23	24	25	26	27
NOV	4	5	6	7	8	9	10
	11	12	13	14	15	16	17
	18	19	20	21	22	23	24
	25	26	27	28	29	30	
DEC	2	3	4	5	6	7	8
	9	10	11	12	13	14	15
	16	17	18	19	20	21	22
	23	24	25	26	27	28	29
	30	31					

Annual preventive maintenance
 U60 undulator chamber installation
 STR all-metal gate valve installation
 SYN magnet measurements
 SYN BM test for 1.2 GeV operation
 BPM electronics adjustment
 BLM system relocation
 SYN RF attenuator repair
 Storage ring vacuum inspection